

General Environmental Incident Summary

Incident: 1946 **Date/Time Notice:** 6/17/2013 1432 **DEM Incident No:**

Responsible Party: Unknown

Date Incident: 6/13/2013 **Time Incident:** 16.50 **Duration:**

County: Williams **Twp:** 154 **Rng:** 99 **Sec:** 19 **Qtr:** NW NW NE

Lat: 48.15440 **Long:** -103.46430 **Method:** Navigation quality GPS

Location Description: N. 48.1544
W. -103.464267

7.5 miles East of Williston, ND on Hwy 1804

Submitted By: Scott Stockdill

Affiliation:

Address:

City:

State:

Zip:

Received By: Scott Stockdill

Contact Person: Scott Stockdill
918 E. Divide Ave., 4th floor
Bismarck, ND 58501

Distance Nearest Occupied Building: 0.3 Miles

Type of Incident: Unidentified Spill on Highway 1804

Description of Released Contaminant: Substance unknown, Sample taken
(WQSJS2013061302) and awaiting lab results.

Volume Spilled: 20.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: No

Cause of Incident:

Exact cause unknown. Spill discovered while driving eastward on Hwy 1804.

Risk Evaluation:

Spill poses no risk

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Spill poses no immediate environmental risks

Action Taken or Planned:

GPS point and photos of location further action dependent upon lab results.

Wastes Disposal Location: Dependent on lab results.

Agencies Involved:

Updates

Date: 6/17/2013 ***Status:*** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

N. 48.1544
W -103.464267

Arrived on location at 4:50 PM 06/13/13.

10-20 gallon spill spotted on HWY 1804 about 7.5 miles East of Williston, ND. Sample (WQSJS2013061302) and photographs taken. Areal impact 1 X 1320 feet on hwy 1804 and 5 X 5 feet on approach to George 19-30-1H well.

No further inspection needed at this time.